

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:

OGM Karl Houskeeper Environmental Scientist III

# **Inspection Report**

Permit Number:	C0150007
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, February 10, 2010
Start Date/Time:	2/10/2010 8:00:00 AM
End Date/Time:	2/10/2010 1:00:00 PM
Last Inspection:	Tuesday, January 12, 2010

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: <u>Clear, Temp. 5 Deg. F.</u> InspectionID Report Number: 2266

Accepted by: jhelfric

3/22/2010

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO MID-CONTINENT REGION

Site: HIDDEN VALLEY MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

#### Mineral Ownership

**Types of Operations** 

✓ Underground

960.00 Total Permitted
6.70 Total Disturbed
6.70 Phase I
Phase II
Phase III

**Current Acreages** 

Federal
State

Fee

Other

County

☐ Surface

☐ Loadout ☐ Processing

Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Jaren Jorgensen from CONSOL was present during the inspection.

Inspector's Signature:

Salf. Muskaper
Environmental Scientist III

Date N

Wednesday, February 10, 2010

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Utan!
Where ideas connect™

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Wednesday, February 10, 2010

Page 2 of 3

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
    b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	<b>✓</b>		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>✓</b>	✓		
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches	<b>✓</b>	✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓	<b>✓</b>		
8.	Noncoal Waste	<b>✓</b>			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control	✓	<b>~</b>		
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	<b>✓</b>		<b>V</b>	

**Inspection Continuation Sheet** 

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Wednesday, February 10, 2010

Page 3 of 3

### 2. Signs and Markers

Mine identification sign is old and dilapidated, but still contains the required information and is legible.

# 4.a Hydrologic Balance: Diversions

Diversion is snow covered.

# 22. Other

Cross country ski tracks present around the site. Probably from recent water monitoring activities.